## **APPENDIX B**

**Site Photographs** 

Photograph 1 – Essential Gas Station gasoline UST area.



Photograph 2 – Essential Gas Station gasoline USTs.



Photograph 3 – Essential Gas Station monitoring well.



Photograph 4 – Essential Gas Station monitoring well.



Photograph 5 – Essential Gas Station heating oil tank.



Photograph 6 – Essential Gas Station 10,000-gallon aboveground diesel tank.



Photograph 7 – Essential Gas Station propane storage tank.



Photograph 8 – Essential Gas Station leach field constructed in 2005.



Photograph 9 – Essential Gas Station leach field vent pipe.



Photograph 10 – View west from MP 105. Photograph 11 – View east from MP 105. Photograph 12 – Indian Valley Gold Mine located at MP 104.

Photograph 13 – Vacant restaurant building west of the Indian House restaurant.



Photograph 14 – Indian House restaurant located at approximately MP 103.5.



Photograph 15 – Rear of Indian Valley restaurant.



Photograph 16 – Turnagain House restaurant located at approximately MP 103.



Photograph 17 – Chugach State Park – Indian Creek. Pit toilets.



Photograph 18 – Brown Bear Saloon located at MP 103.



Photograph 19 – Jim's Liquor located at MP 103.



Photograph 20 – House and garage located east of Jim's Liquor.



Photograph 21 – Northwest view of Jim's Liquor and another small house.



Photograph 22 – Valley Bible Chalet located east of Jim's Liquor.



Photograph 23 – Bird Creek access parking area located at MP 101.5.



Photograph 24 – Bird Creek parking lot.



Photograph 25 – Bird Creek Campground located on the south side of the Seward Highway at approximately MP 101.3.



Photograph 26 – Bird Ridge Café located east of the Essential Gas Station at MP 101.



Photograph 27 – View west from the Bird Ridge Café to the Essential Gas Station.



Photograph 28 – Bird Ridge Café septic system located approximately 50 feet north of the Seward Highway.



Photograph 29 – Motel rooms located behind the Bird Ridge Café.



Photograph 30 – Birdhouse Garage located at the intersection of Konikson Road and the Seward Highway.



Photograph 31 – Additional view of the Birdhouse Garage.



Photograph 32 – Log structure being developed north of the Seward Highway at approximately MP 99.5.

